

FIRE APPLIANCES SERVICE REPORT

PREMISES INFORMATION

Site Name:	Westwood parish church
Site Address:	East Kilbride
Date:	Dec 6, 2023
Job Number:	811962

SERVICED - ITEM

SERVICED - ITEM	1 OF 3
-----------------	--------

Appliance Type	Water Extinguisher
Service Completed	Basic Annual Service
Quantity	6

SERVICED - ITEM	2 OF 3
-----------------	--------

Appliance Type	Co2 Extinguisher
Service Completed	Basic Annual Service
Quantity	3

SERVICED - ITEM	3 OF 3
-----------------	--------

Appliance Type	Fire Blanket
Service Completed	Basic Annual Service
Quantity	1

SERVICED TOTALS

Basic Annual Service Total	10
----------------------------	----

INFORMATION

Clients responsible person:

Responsible persons have obligations under fire legislation to use a competent person to maintain extinguishing equipment in an efficient state, in efficient working order and in good repair, an appropriate level of fire fighting equipment must be maintained at all times to safeguard employees in the event of fire.

Visual monthly inspection:

The responsible person should carry out visual inspections of all extinguishers regularly. These visual inspections should be carried out at least monthly. When circumstances require, inspections should be carried out more frequently. The responsible person should record the results of these visual inspections and arrange for corrective action, where necessary, by a competent person. In the event of doubt, the responsible person should arrange for a competent person to examine the extinguisher.

Basic Service:

The maintenance intervals for the basic service (12 months) have a tolerance of ± 1 month.

Extended service:

The maintenance intervals for extended service is every 5 years, this includes for water, water based and powder extinguishers, the extended service incorporates the full discharge testing and refill of the extinguisher, this may or may not be included within your service plan.

Overhaul service:

The maintenance intervals for overhaul service is every 10 years, this includes for carbon dioxide extinguishers, the overhaul service incorporates the full discharge testing, pressure testing of the extinguisher body, replacement valve / headcap and refill of the extinguisher, this may or may not be included within your service plan.

Not Maintained:

If the required spare parts are not available for any of the extinguishers, the maintenance should be interrupted and the extinguisher made safe, removed from its designated place and marked "NOT MAINTAINED",

Condemned:

Any extinguisher with a major defect or defects which make it unsafe for use, and which cannot be rectified during maintenance, removed from its designated place and marked "CONDEMNED",

COMMENTS

Comments

PARTS USED - ITEM

PARTS USED - ITEM

1 OF 1

Part Description

Anti tamper tag

Quantity of Part Used

9

NAME & SIGNATURE

Vipond Engineer Signature




Vipond Engineer Print Name

Michael McIlmunn

Date / time

Dec 6, 2023 3:06:30 PM
GMT

Customer Signature



Customer Print Name

Liz

Date / time

Dec 6, 2023 3:06:30 PM
GMT

Email Copy of Service Report

property@westwood-
church.org.uk

Service Completed?

Yes

We confirm that our representative has completed their duties at the above premises apart from inspecting / servicing any non conforming extinguishers as recorded all portable extinguishers have been inspected / serviced in accordance with BS 5306: 3 2009, where applicable all hose reels have been serviced in accordance with BS EN 671: 3 2000.