



FIRE MAINTENANCE CERTIFICATE

Page 1 of 2

ENGINEER'S NAME		WEST > PHILIP GORDON > MULTI (M)			DATE OF CALL		10/05/2023	
CUSTOMER NAME		Westwood Church				CONTRACT REF :		4102
ADDRESS :		Belmont Drive, Westwood, G75 8HD						
SYSTEM :		Fire Detection and Alarm System BS5839 Pt 1						
LAST INSPECTION DATE:		23/12/2022		NEXT INSPECTION DATE:		01/10/2023		CALL REF : 1639165
DEVICE TYPE CHECKED	CALL POINT (CP)	YES	SMOKE DETECTOR (SD)	YES	HEAT DETECTOR (HD)	YES	SOUNDER (SO)	YES
SYSTEM TYPE		Conventional			SIGNALLING		Audible	
FALSE ALARM ANALYSIS	False Alarm Rate OK?	YES	No. of Devices	8		No. of False Alarms	0	
DOES THE NUMBER OF FALSE ALARMS EXCEED 1 PER 25 DETECTORS?							NO	
DB LEVELS TESTED		YES			RESULTS =		PASS	

ZONES / LOOPS TESTED :

Noted Structural Changes :				
BATTERY RESULTS – VOLTS DC			PASS	
Battery Test	Quiescent Ma =	0	FIRE PANEL MANUFACTURER	C-TEC
	Alarm mA =	0	DEVICE MANUFACTURER	APOLLO




Authorised and regulated by the Financial Conduct Authority



FIRE MAINTENANCE CERTIFICATE

Page 2 of 2

No	CHECK/TEST	TICK
1	Has the structure of the building changed?	NO
2	Has the use of the building or part of the building changed?	NO
3	Routine Maintenance in accordance with BS5839-1:2017	YES
4	Examine system logbook and ensure that any recorded faults have received appropriate attention	YES
5	Check the installation and siting of all equipment against the specification fitted drawings/notes	YES
6	Check the satisfactory operation of detection and log all devices tested above	YES
7	Inspect all flexible connections	YES
8	Check printers for correct operation and legible characters	N/A
9	Check stand-by power for correct charging rates and battery capacities and test with the mains disconnected.	CHECKED - PASS
10	Check age and condition of batteries including all external PSU's and replace if required.	REPLACED BATTERY
11	Check control panel for correct operation, plus date/.time	PASS
12	Check remote signalling – where applicable to ARC	N/A
13	Check audible and visual warning devices	CHECKED
14	Check alarm system is fully functional and note any areas for future attention	ALL OK
15	Clean equipment as required – i.e. visual alarm devices	N/A
16	Check that the keyholder information is up to date record any changes on this docket.	N/A
COMMENTS		N/A
CUSTOMER'S NAME :		Susan Taylor
CUSTOMER SIGNATURE :		
ENGINEER'S NAME :		WEST > PHILIP GORDON > MULTI (M)
ENGINEER'S SIGNATURE		

